




Assembly Instructions




① = 4 PCS




② = 2 PCS




③ = 2 PCS





④ = 4 PCS



⑤ = 1 PC




⑥ = 1 PC




STEP 1

No	Dimension	Picture	Qty
A	M6 x 50		16
B	Vis 4 x 30		16
C	M4		1


Assembly Instructions




① = 4 PCS




② = 2 PCS




③ = 2 PCS




④ = 4 PCS



⑤ = 1 PC



⑥ = 1 PC



STEP 2

No	Dimension	Picture	Qty
A	M6 x 50		16
B	Vis 4 x 30		16
C	M4		1